



报告编号	结论	报告日期	影像资料
DAJC-7F01019-2022	合格	2022-3-17	
DAJC-7F01025~026-2022	合格	2022-4-13	
DAJC-7F02017-2022	合格	2022-3-17	
DAJC-7F02018~019-2022	合格	2022-3-28	




报告编号	结论	报告日期	影像资料
DAJC-7F02020~021-2022	合格	2022-4-3	
DAJC-7F02022-2022	合格	2022-4-4	
DAJC-7F03009-2022	合格	2022-3-12	
DAJC-7F03010~011-2022	合格	2022-3-18	
DAJC-7F03016-2022	合格	2022-3-27	

报告编号	结论	报告日期	影像资料
DAJC-7F03018-2022	合格	2022-4-3	
DAJC-7F03019~020-2022	合格	2022-4-5	
DAJC-7F04043~044-2022	合格	2022-3-17	
DAJC-7F04049-2022	合格	2022-3-27	

报告编号	结论	报告日期	影像资料
DAJC-7F05034~036-2022	合格	2022-3-17	 经度: 120.205771 纬度: 37.300428 地址: 山东省烟台市招远市金岭 镇栗山村 时间: 2022-03-17 03:44:10 海拔: 88.4米
DAJC-7F05041-2022	合格	2022-3-27	
DAJC-7F05045~046-2022	合格	2022-3-28	 经度: 120.295382 纬度: 37.088550 地址: 山东省青岛市莱西市307 省道山东黄金矿业(莱西)有限公 司 时间: 2022-03-28 10:30:44 海拔: 176.9米 经度: 120.295389 纬度: 37.088490 地址: 山东省青岛市莱西市307 省道山东黄金矿业(莱西)有限公 司 时间: 2022-03-28 10:30:55 海拔: 181.1米



报告编号	结论	报告日期	影像资料
DAJC-7F05047-2022	合格	2022-4-3	 电话: 120 538511 手机: 1374491337 地址: 山东省烟台莱州市 莱州金矿东矿区中深区 日期: 2022-04-03 14:48:37 海拔: 172.3米 电话: 120 538511 手机: 1374491337 地址: 山东省烟台莱州市 莱州金矿东矿区中深区 日期: 2022-04-03 海拔: 269.0米
DAJC-7F06001-2022	合格	2022-3-12	
DAJC-7F06002~003-2022	合格	2022-3-18	
DAJC-7F10067-2022	合格	2022-3-2	 电话: 120 095414 手机: 137 389364 地址: 山东省烟台莱州市 莱州金矿东矿区中深区 日期: 2022-03-02 11:58:24 海拔: 38.2米


报告编号	结论	报告日期	影像资料
DAJC-7F10077-2022	合格	2022-3-12	 
DAJC-7F10094~095-2022	合格	2022-3-15	 
DAJC-7F10102~103-2022	合格	2022-3-17	 
DAJC-7F10104~105-2022	合格	2022-3-18	 


报告编号	结论	报告日期	影像资料
DAJC-7F10140~142-2022	合格	2022-4-3	 经度: 120.538448 纬度: 37.449796 地址: 山东省烟台市招远市玲珑镇 东风矿区生活区 时间: 2022-04-03 13:11:33 海拔: 319.6米 经度: 120.574348 纬度: 37.468591 地址: 山东省烟台市招远市田庄镇 远市公安检查站南侧卡点 时间: 2022-04-03 13:59:42 海拔: 228.9米
DAJC-7F10143-2022	合格	2022-4-4	 经度: 120.549318 纬度: 37.453978 地址: 山东省烟台市招远市九福路 嘉九福路隧道 时间: 2022-04-04 09:41:07 海拔: 240.8米 经度: 120.549768 纬度: 37.454060 地址: 山东省烟台市招远市九福路 嘉九福路隧道 时间: 2022-04-04 09:39:56 海拔: 0.0米
DAJC-7F10144~146-2022	合格	2022-3-27	
DAJC-7F10148~149-2022	合格	2022-4-5	


报告编号	结论	报告日期	影像资料
DAJC-7F10163-2022	合格	2022-5-6	
DAJC-7F11113~115-2022	合格	2022-3-18	
DAJC-7F11142~145-2022	合格	2022-3-17	 
DAJC-7F11172~174-2022	合格	2022-4-9	 



报告编号	结论	报告日期	影像资料
DAJC-7F11175~179-2022	合格	2022-4-12	
DAJC-7F11198-2022	合格	2022-5-6	
DAJC-7F12022-2022	合格	2022-3-12	
DAJC-7F12039~041-2022	合格	2022-3-18	

报告编号	结论	报告日期	影像资料
DAJC-7F12045-2022	合格	2022-4-3	
DAJC-7F12050~051-2022	合格	2022-4-5	
DAJC-7F12054-2022	合格	2022-4-9	
DAJC-7F12055~056-2022	合格	2022-4-10	


报告编号	结论	报告日期	影像资料
DAJC-7F12061~062-2022	合格	2022-5-6	
DAJC-7F13113~115-2022	合格	2022-3-12	
DAJC-7F13176~188-2022	合格	2022-3-18	
DAJC-7F13207~211-2022	合格	2022-4-3	


报告编号	结论	报告日期	影像资料
DAJC-7F13229~235-2022	合格	2022-4-5	
DAJC-7F13247~252-2022	合格	2022-4-9	
DAJC-7F13253~258-2022	合格	2022-4-10	
DAJC-7F13274~279-2022	合格	2022-5-6	

报告编号	结论	报告日期	影像资料
DAJC-7F141099~1110-2022	合格	2022-4-13	
DAJC-7F141198~1200-2022	合格	2022-4-13	
DAJC-7F14364~372-2022	合格	2022-3-11	
DAJC-7F14416~444-2022	合格	2022-3-12	

报告编号	结论	报告日期	影像资料
DAJC-7F14445~463-2022	合格	2022-3-13	
DAJC-7F14464~516-2022	合格	2022-3-14	
DAJC-7F14517~552-2022	合格	2022-3-15	



报告编号	结论	报告日期	影像资料
DAJC-7F14553~586-2022	合格	2022-3-16	 
DAJC-7F14587~632-2022	合格	2022-3-17	 
DAJC-7F14633~646-2022	合格	2022-3-18	 
DAJC-7F14647~657-2022	合格	2022-3-13	


报告编号	结论	报告日期	影像资料
DAJC-7F14658~666-2022	合格	2022-3-15	
DAJC-7F14667~672-2022	合格	2022-3-18	
DAJC-7F14673~703-2022	合格	2022-3-11	
DAJC-7F14715~727-2022	合格	2022-3-12	

报告编号	结论	报告日期	影像资料
DAJC-7F14728~755-2022	合格	2022-3-13	
DAJC-7F14756~794-2022	合格	2022-3-14	
DAJC-7F14795~805-2022	合格	2022-3-15	
DAJC-7F14806~854-2022	合格	2022-3-16	

报告编号	结论	报告日期	影像资料
DAJC-7F14855~862-2022	合格	2022-3-18	
DAJC-7F14987~998-2022	合格	2022-3-12	 
DAJC-7F15125~131-2022	合格	2022-3-11	 
DAJC-7F15138~140-2022	合格	2022-3-12	  


报告编号	结论	报告日期	影像资料
DAJC-7F15160~172-2022	合格	2022-3-11	
DAJC-7F15173~174-2022	合格	2022-3-12	
DAJC-7F15175~185-2022	合格	2022-3-14	
DAJC-7F15186~191-2022	合格	2022-3-15	


报告编号	结论	报告日期	影像资料
DAJC-7F15192~193-2022	合格	2022-3-18	
DAJC-7F15194-2022	合格	2022-3-15	
DAJC-7F15195~196-2022	合格	2022-3-18	
DAJC-7F15197~201-2022	合格	2022-3-11	



报告编号	结论	报告日期	影像资料
DAJC-7F15202~206-2022	合格	2022-3-15	
DAJC-7F15207~209-2022	合格	2022-3-12	
DAJC-7F15210~211-2022	合格	2022-3-13	

报告编号	结论	报告日期	影像资料
DAJC-7F15212-2022	合格	2022-3-16	 电话: 119-91637 地址: 77-25180 地址: 山东烟台莱州市 大前合利村村委会 日期: 2022-03-16 16:14:00 地址: 112-25180 电话: 119-91637 地址: 77-25180 地址: 山东烟台莱州市 大前合利村村委会 日期: 2022-03-16 16:14:00 地址: 112-25180
DAJC-7F15213~217-2022	合格	2022-3-13	 
DAJC-7F15218~225-2022	合格	2022-3-14	 
DAJC-7F15233~242-2022	合格	2022-3-16	 电话: 119-942287 地址: 37-386658 地址: 山东烟台莱州市 大前合利村村委会 日期: 2022-03-16 16:14:00 地址: 112-25180

报告编号	结论	报告日期	影像资料
DAJC-7F15243~248-2022	合格	2022-3-12	
DAJC-7F15249-2022	合格	2022-3-14	
DAJC-7F15250~251-2022	合格	2022-3-13	 
DAJC-7F15252~260-2022	合格	2022-3-15	

报告编号	结论	报告日期	影像资料
DAJC-7F15261~266-2022	合格	2022-3-16	
DAJC-7F15267~275-2022	合格	2022-3-18	
DAJC-7F15324~326-2022	合格	2022-4-13	

报告编号	结论	报告日期	影像资料
DAJC-7F15346-2022	合格	2022-4-13	
DAJC-7F15347-2022	合格	2022-4-17	
DAJC-7F16214~217-2022	合格	2022-3-12	
DAJC-7F16232~237-2022	合格	2022-3-14	

报告编号	结论	报告日期	影像资料
DAJC-7F16238-2022	合格	2022-3-15	
DAJC-7F16239~250-2022	合格	2022-3-13	
DAJC-7F16251~261-2022	合格	2022-3-15	
DAJC-7F16262~267-2022	合格	2022-3-16	



报告编号	结论	报告日期	影像资料
DAJC-7F16268~273-2022	合格	2022-3-17	 经纬度: 119.885955 海拔: 37.800288 地址: 山东省烟台市莱州市莱州港98号莱州市 大港石油公司 时间: 2022-03-17 10:05:11 经纬度: 119.885955 海拔: 37.800288 地址: 山东省烟台市莱州市莱州港98号莱州市 大港石油公司 时间: 2022-03-17 10:05:11
DAJC-7F16274~275-2022	合格	2022-3-18	 经纬度: 119.885955 海拔: 37.800288 地址: 山东省烟台市莱州市莱州港98号莱州市 大港石油公司 时间: 2022-03-17 10:05:11 经纬度: 119.885955 海拔: 37.800288 地址: 山东省烟台市莱州市莱州港98号莱州市 大港石油公司 时间: 2022-03-17 10:05:11
DAJC-7F16276-2022	合格	2022-3-16	 经纬度: 119.927433 海拔: 37.877251 地址: 山东省烟台市莱州市莱州港1727号莱州市 大港石油公司 时间: 2022-03-16 10:24:41 经纬度: 119.927433 海拔: 37.877251 地址: 山东省烟台市莱州市莱州港1727号莱州市 大港石油公司 时间: 2022-03-16 10:24:41
DAJC-7F16278~293-2022	合格	2022-3-11	 经纬度: 119.941565 海拔: 37.87932 地址: 山东省烟台市莱州市永福 路105号金水苑 时间: 2022-03-11 14:25:28 海拔: 62.1米 经纬度: 119.940667 海拔: 37.87875 地址: 山东省烟台市莱州市永福 路105号金水苑 时间: 2022-03-11 14:35:34 海拔: 62.6米

报告编号	结论	报告日期	影像资料
DAJC-7F16294~302-2022	合格	2022-3-12	
DAJC-7F16307~310-2022	合格	2022-3-12	
DAJC-7F16311~322-2022	合格	2022-3-13	 经度: 119.947434 纬度: 37.399569 地址: 山东省烟台市莱州市城港路299号莱州市三山路道路运输管理所 时间: 2022-03-13 09:18:52 海拔: 0.0米 经度: 119.947434 纬度: 37.399569 地址: 山东省烟台市莱州市城港路299号莱州市三山路道路运输管理所 时间: 2022-03-13 09:19:49 海拔: 0.0米
DAJC-7F16323~327-2022	合格	2022-3-14	



报告编号	结论	报告日期	影像资料
DAJC-7F16329~332-2022	合格	2022-3-11	
DAJC-7F16333-2022	合格	2022-3-14	
DAJC-7F16336~339-2022	合格	2022-3-15	
DAJC-7F16340~357-2022	合格	2022-3-16	 经度: 119.941773 纬度: 37.390607 地址: 山东省烟台市莱州市永福 路新立金矿温井公司 时间: 2022-03-16 14:44:36 海拔: 0.0米 经度: 119.945965 纬度: 37.398315 地址: 山东省烟台市莱州市城港 路299号三山岛大桥 时间: 2022-03-16 08:24:46 海拔: -14.2米

报告编号	结论	报告日期	影像资料
DAJC-7F16358~359-2022	合格	2022-3-14	
DAJC-7F16360~370-2022	合格	2022-3-17	
DAJC-7F16389~390-2022	合格	2022-4-13	
DAJC-7F16441-2022	合格	2022-4-17	 


报告编号	结论	报告日期	影像资料
DAJC-7F16442~443-2022	合格	2022-4-18	
DAJC-7F17041~046-2022	合格	2022-3-12	
DAJC-7F17047~058-2022	合格	2022-3-14	
DAJC-7F17059~062-2022	合格	2022-3-15	

报告编号	结论	报告日期	影像资料
DAJC-7F17063~066-2022	合格	2022-3-12	
DAJC-7F22112~117-2022	合格	2022-3-13	
DAJC-7F22118~119-2022	合格	2022-3-18	
DAJC-7F23035-2022	合格	2022-3-11	

报告编号	结论	报告日期	影像资料
DAJC-7F23071~072-2022	合格	2022-4-16	经度: 120.120772 纬度: 37.389656 地址: 山东省烟台市莱州市206 国道文丰村 时间: 2022-04-16 13:27:05 海拔: 0.0米 经度: 120.120812 纬度: 37.389652 地址: 山东省烟台市莱州市206 莱州文丰机械有限公司 时间: 2022-04-16 13:44:22 海拔: 53.3米 经度: 120.125048 纬度: 37.396805 地址: 山东省烟台市莱州市206 莱州文丰机械有限公司 时间: 2022-04-16 13:27:05 海拔: 0.0米
DAJC-7F23073-2022	合格	2022-4-14	经度: 120.116623 纬度: 37.378647 地址: 山东省烟台市莱州市大寨 莱州文丰机械有限公司 时间: 2022-04-14 06:45:23 海拔: 0.0米 经度: 120.109825 纬度: 37.386428 地址: 山东省烟台市莱州市206 莱州文丰机械有限公司 时间: 2022-04-14 09:45:11 海拔: 51.9米
DAJC-7F23074~080-2022	合格	2022-4-15	经度: 120.130784 纬度: 37.400469 地址: 山东省烟台市莱州市206 国道焦家金矿职工医院 时间: 2022-04-15 14:15:08 海拔: 0.0米 经度: 120.130867 纬度: 37.400448 地址: 山东省烟台市莱州市206 莱州文丰机械有限公司 时间: 2022-04-15 06:10:13 海拔: 50.4米

报告编号	结论	报告日期	影像资料
DAJC-7F23081~082-2022	合格	2022-4-16	
DAJC-7F24018~019-2022	合格	2022-3-12	
DAJC-7F24020~022-2022	合格	2022-3-14	
DAJC-7F24023-2022	合格	2022-3-18	

报告编号	结论	报告日期	影像资料
DAJC-7F32089~090-2022	合格	2022-5-6	
DAJC-7F50030-2022	合格	2022-4-17	
DAJC-7F50031-2022	不合格	2022-5-8	
DAJC-7F61010~011-2022	合格	2022-2-26	

报告编号	结论	报告日期	影像资料
DAJC-7F61024~025-2022	合格	2022-3-28	
DAJC-7F61026-2022	合格	2022-4-13	 
DAJC-7F38413-2022	合格	2022-4-24	/
DAJC-7F38414-2022	合格	2022-4-25	/
DAJC-7F38415-2022	合格	2022-4-26	/
DAJC-7F38416-2022	合格	2022-4-27	/
DAJC-7F38417-2022	合格	2022-4-28	/
DAJC-7F38427-2022	合格	2022-4-29	/
DAJC-7F38428~429-2022	合格	2022-4-29	/
DAJC-7F38430~431-2022	合格	2022-4-30	/
DAJC-7F38433-2022	合格	2022-5-5	/
DAJC-7F38434-2022	合格	2022-5-5	/
DAJC-7F38435~436-2022	合格	2022-5-6	/
DAJC-7F38437-2022	合格	2022-5-7	/
DAJC-7F38440-2022	合格	2022-5-6	/
DAJC-7F38441~442-2022	合格	2022-5-7	/
DAJC-7F38443-2022	合格	2022-5-8	/

报告编号	结论	报告日期	影像资料
DAJC-7F38444~445-2022	合格	2022-5-9	/
DAJC-7F38446-2022	合格	2022-5-10	/
DAJC-7F38447-2022	合格	2022-5-10	/
DAJC-7F38448-2022	合格	2022-5-9	/
DAJC-7F38449-2022	合格	2022-5-10	/
DAJC-7F38450~451-2022	合格	2022-5-11	/
DAJC-7F38452~453-2022	合格	2022-5-12	/
DAJC-7F38454-2022	合格	2022-5-13	/
DAJC-7F38455-2022	合格	2022-5-14	/
DAJC-7F38456~457-2022	合格	2022-5-15	/
DAJC-7F38458-2022	合格	2022-5-16	/
DAJC-7F38459-2022	合格	2022-5-17	/
DAJC-7F38460-2022	合格	2022-5-18	/
DAJC-7F38484-2022	合格	2022-5-15	/
DAJC-7F38485-2022	合格	2022-5-13	/
DAJC-7F38487-2022	合格	2022-5-13	/
DAJC-7F38488-2022	合格	2022-5-14	/
DAJC-7F38517~518-2022	合格	2022-5-22	/
DAJC-7F46058-2022	合格	2022-4-17	/
DAJC-7F47091~093-2022	合格	2022-4-7	/
DAJC-7F47094~098-2022	合格	2022-4-10	/
DAJC-7F47109-2022	合格	2022-5-4	/
DAJC-7F83014-2022	合格	2022-4-29	/