













报告编号	结论	报告日期	影像资料
DAJC-7F01067~068-2022	合格	2022-6-20	 <p> 经度: 119.956390 纬度: 37.410201 地址: 山东烟台莱州市三山岛街道 莱州港 时间: 2022-06-20 08:17:40 备注: 长陵水印编辑备注 </p> <p> 经度: 119.956101 纬度: 37.403980 地址: 山东烟台莱州市三山岛街 道 中国工商银行(烟台莱州三山岛分 处) 时间: 2022-06-20 09:45:40 备注: 长陵水印编辑备注 </p>
DAJC-7F01079~080-2022	合格	2022-8-6	
DAJC-7F03069~070-2022	合格	2022-8-23	
DAJC-7F04160-2022	合格	2022-8-20	 <p> 经度: 120.115874 纬度: 37.424323 地址: 山东省烟台市莱州市金岭街 159号西草坡村 时间: 2022-08-20 15:16:09 </p> <p> 经度: 120.115904 纬度: 37.424230 地址: 山东省烟台市莱州市金岭街 159号西草坡村 时间: 2022-08-20 15:16:09 </p>
DAJC-7F04161~162-2022	合格	2022-8-23	




报告编号	结论	报告日期	影像资料
DAJC-7F04163-2022	合格	2022-8-26	
DAJC-7F04164~165-2022	合格	2022-8-21	
DAJC-7F04166-2022	合格	2022-9-2	
DAJC-7F05124-2022	合格	2022-8-9	



报告编号	结论	报告日期	影像资料
DAJC-7F05125-2022	合格	2022-8-16	 <p> 号数: 114-50318 纬度: 35.950640 地址: 山东省泰安市东平县2A3省道路南 掘进工作面掌子面 时间: 2022-08-16 11:54:32 </p> <p> 号数: 116-527900 纬度: 35.988085 地址: 山东省泰安市东平县2A3省道路南 掘进工作面掌子面 时间: 2022-08-16 11:51:46 </p>
DAJC-7F10360-2022	合格	2022-8-6	
DAJC-7F10361-2022	合格	2022-8-7	
DAJC-7F10362-2022	合格	2022-8-9	 <p> 号数: 110-000000 纬度: 37.375294 地址: 山东省泰安市东平县2A3省道路南 掘进工作面掌子面 时间: 2022-08-09 07:44:55 海拔: 23.0米 天气: 晴 23-22℃ 东北风 </p> <p> 号数: 120-093087 纬度: 37.374738 地址: 山东省泰安市东平县2A3省道路南 掘进工作面掌子面 时间: 2022-08-09 07:44:55 海拔: 23.0米 天气: 晴 23-22℃ 东北风 </p>




报告编号	结论	报告日期	影像资料
DAJC-7F10387~392-2022	合格	2022-8-17	
DAJC-7F10393-2022	合格	2022-8-20	
DAJC-7F10396-2022	合格	2022-8-16	
DAJC-7F10398-2022	合格	2022-8-25	


报告编号	结论	报告日期	影像资料
DAJC-7F11382~390-2022	合格	2022-8-25	
DAJC-7F12115~116-2022	合格	2022-8-6	
DAJC-7F12119-2022	合格	2022-8-7	
DAJC-7F12124-2022	合格	2022-8-26	


报告编号	结论	报告日期	影像资料
DAJC-7F13539~543-2022	合格	2022-8-6	
DAJC-7F13548~552-2022	合格	2022-8-5	
DAJC-7F13553~562-2022	合格	2022-8-4	 <p>工程：洞修工程 地点：洞修工程 时间：洞修工程 海拔：洞修工程 天气：洞修工程</p>
DAJC-7F13569~573-2022	合格	2022-8-7	


报告编号	结论	报告日期	影像资料
DAJC-7F13575~578-2022	合格	2022-8-4	
DAJC-7F13591~598-2022	合格	2022-8-26	
DAJC-7F142601~2621-2022	合格	2022-8-4	
DAJC-7F142622~2631-2022	合格	2022-8-7	




报告编号	结论	报告日期	影像资料
DAJC-7F142632~2643-2022	合格	2022-8-11	 <p>The top photograph shows four workers in safety gear standing in front of a 10kV substation enclosure. The bottom photograph shows workers inside a control room, with one worker kneeling and another standing near a control panel.</p>
DAJC-7F142644~2654-2022	合格	2022-8-12	 <p>The left photograph shows a worker kneeling on the floor in a control room, working on equipment. The right photograph shows a worker standing and inspecting a control panel.</p>
DAJC-7F142655~2677-2022	合格	2022-8-13	 <p>The top-left photograph shows a worker kneeling in a control room. The top-right photograph shows two workers standing near a control panel. The bottom-left photograph shows a worker kneeling in a control room.</p>
DAJC-7F142678~2680-2022	合格	2022-8-13	 <p>The left photograph shows workers in a control room, with one worker kneeling. The right photograph shows a worker standing and inspecting a control panel.</p>


报告编号	结论	报告日期	影像资料
DAJC-7F142681~2690-2022	合格	2022-8-14	
DAJC-7F142691~2716-2022	合格	2022-8-15	
DAJC-7F142717~2726-2022	合格	2022-8-14	
DAJC-7F142727~2731-2022	合格	2022-8-16	



报告编号	结论	报告日期	影像资料
DAJC-7F142736~2739-2022	合格	2022-8-16	
DAJC-7F142740~2753-2022	合格	2022-8-17	
DAJC-7F142754~2764-2022	合格	2022-8-16	
DAJC-7F142815~2829-2022	合格	2022-8-17	


报告编号	结论	报告日期	影像资料
DAJC-7F142830~2835-2022	合格	2022-8-18	
DAJC-7F142836~2840-2022	合格	2022-8-17	
DAJC-7F142841~2846-2022	合格	2022-8-19	
DAJC-7F142847~2866-2022	合格	2022-8-21	





报告编号	结论	报告日期	影像资料
DAJC-7F142867~2871-2022	合格	2022-8-24	
DAJC-7F142872~2907-2022	合格	2022-8-22	
DAJC-7F142908~2920-2022	合格	2022-8-23	
DAJC-7F142921~2923-2022	合格	2022-8-26	


报告编号	结论	报告日期	影像资料
DAJC-7F142924~2936-2022	合格	2022-8-24	
DAJC-7F142937~2961-2022	合格	2022-8-25	
DAJC-7F142962~2976-2022	合格	2022-8-26	
DAJC-7F15829~836-2022	合格	2022-8-4	

报告编号	结论	报告日期	影像资料
DAJC-7F15857~858-2022	合格	2022-8-7	 <p>经纬: 120.502965 纬度: 37.463641 地址: 山东省烟台莱州市213省道 持续检测 时间: 2022-08-07 15:52:34 海拔: 209.3米 天气: 34~33℃ 西南风</p>
DAJC-7F15859~865-2022	合格	2022-8-12	 <p>经纬: 120.517608 纬度: 37.401602 地址: 山东省烟台莱州市莱州矿综合门诊部 持续检测 时间: 2022-08-12 10:07:11</p>
DAJC-7F15866~868-2022	合格	2022-8-13	
DAJC-7F15869~873-2022	合格	2022-8-14	

报告编号	结论	报告日期	影像资料
DAJC-7F15874~875-2022	合格	2022-8-15	
DAJC-7F15876~878-2022	合格	2022-8-16	
DAJC-7F15879~881-2022	合格	2022-8-17	
DAJC-7F15882~885-2022	合格	2022-8-18	


报告编号	结论	报告日期	影像资料
DAJC-7F15890~891-2022	合格	2022-8-19	
DAJC-7F15896~898-2022	合格	2022-8-22	
DAJC-7F15900~901-2022	合格	2022-8-24	
DAJC-7F15902~903-2022	合格	2022-8-24	

报告编号	结论	报告日期	影像资料
DAJC-7F15904-2022	合格	2022-8-21	
DAJC-7F15905-2022	合格	2022-8-22	
DAJC-7F15906~908-2022	合格	2022-8-23	
DAJC-7F15909~914-2022	合格	2022-8-25	


报告编号	结论	报告日期	影像资料
DAJC-7F15915~919-2022	合格	2022-8-26	
DAJC-7F15920~921-2022	合格	2022-8-12	 <p>经纬: 116.336274 纬度: 35.992958 地址: 山东省泰安市东平县243省道 鲁源派出所水河警务区 时间: 2022-08-12 14:00:18 海拔: 53.1米 天气: 34~34℃ 南风 备注: 长梭水印偏镇备注</p> <p>经纬: 116.336233 纬度: 35.986555 地址: 山东省泰安市东平县水河路 水河 时间: 2022-08-12 13:59:50 海拔: 52.8米 天气: 34~34℃ 南风 备注: 长梭水印偏镇备注</p>
DAJC-7F16826~835-2022	合格	2022-8-4	 <p>经纬: 116.311798 纬度: 36.040303 地址: 山东省泰安市东平县152国道 时间: 2022-08-04 15:31:45</p>
DAJC-7F16836~841-2022	合格	2022-8-7	 <p>经纬: 120.504359 纬度: 37.459404 地址: 山东省烟台市招远市213省道 山东中(岭北)有限公司职工医院 时间: 2022-08-07 13:21:19 海拔: 213.0米 天气: 32~33℃ 西南风</p> <p>经纬: 120.503596 纬度: 37.457884 地址: 山东省烟台市招远市213省道 检修山庄 时间: 2022-08-07 14:46:53 海拔: 213.2米 天气: 32~33℃ 西南风</p>

报告编号	结论	报告日期	影像资料
DAJC-7F16842~853-2022	合格	2022-8-11	 <p>经纬: 120.130909 纬度: 37.400659 地址: 山东省烟台市莱州市226国道 莱州金矿综合门诊部 时间: 2022-08-11 15:07:05</p> <p>经纬: 120.131129 纬度: 37.400546 地址: 山东省烟台市莱州市206国道 莱州金矿综合门诊部 时间: 2022-08-11 10:04:07</p>
DAJC-7F16854~864-2022	合格	2022-8-12	 <p>经纬: 120.136459 纬度: 37.401672 地址: 山东省烟台市莱州市莱州金矿综合门诊部 时间: 2022-08-12 08:42:16</p> <p>经纬: 120.136644 纬度: 37.401838 地址: 山东省烟台市莱州市莱州金矿综合门诊部 时间: 2022-08-12 15:10:35</p>
DAJC-7F16865~876-2022	合格	2022-8-13	 <p>经纬: 120.130422 纬度: 37.401922 地址: 山东省烟台市莱州市226国道 莱州金矿综合门诊部 时间: 2022-08-13 08:30:37</p> <p>经纬: 120.132232 纬度: 37.402300 地址: 山东省烟台市莱州市206国道 莱州金矿综合门诊部 时间: 2022-08-13 15:05:34</p>
DAJC-7F16877~889-2022	合格	2022-8-14	 <p>经纬: 120.130452 纬度: 37.401659 地址: 山东省烟台市莱州市228国道 金矿建设 时间: 2022-08-14 13:50:39</p> <p>经纬: 120.131826 纬度: 37.402171 地址: 山东省烟台市莱州市228国道 金矿综合门诊部 时间: 2022-08-14 15:08:11</p>



报告编号	结论	报告日期	影像资料
DAJC-7F16890~893-2022	合格	2022-8-15	
DAJC-7F16894~896-2022	合格	2022-8-16	
DAJC-7F16897~903-2022	合格	2022-8-17	
DAJC-7F16904~905-2022	合格	2022-8-18	



报告编号	结论	报告日期	影像资料
DAJC-7F16918~920-2022	合格	2022-8-24	
DAJC-7F16921~926-2022	合格	2022-8-20	 
DAJC-7F16927~934-2022	合格	2022-8-21	 
DAJC-7F16935~938-2022	合格	2022-8-22	  

报告编号	结论	报告日期	影像资料
DAJC-7F16939~940-2022	合格	2022-8-24	
DAJC-7F16941~942-2022	合格	2022-8-25	
DAJC-7F16943~945-2022	合格	2022-8-26	
DAJC-7F16946~950-2022	合格	2022-8-23	




报告编号	结论	报告日期	影像资料
DAJC-7F17141~143-2022	合格	2022-8-5	 <p> 经纬度: 116.316962 东经: 36.040540 地址: 山东泰安东平县 时间: 2022-08-05 </p>
DAJC-7F17144~149-2022	合格	2022-8-15	
DAJC-7F17150~158-2022	合格	2022-8-22	
DAJC-7F17159~163-2022	合格	2022-8-24	

报告编号	结论	报告日期	影像资料
DAJC-7F22452~453-2022	合格	2022-8-11	 <p>经度: 120.131357 纬度: 37.400751 地址: 山东省烟台市莱州市206国道 焦家金矿综合门诊部 时间: 2022-08-11 14:54:03</p> <p>经度: 120.131142 纬度: 37.400708 地址: 山东省烟台市莱州市焦家金矿综合门诊部 时间: 2022-08-11 14:56:05</p>
DAJC-7F22454~455-2022	合格	2022-8-13	 <p>经度: 120.131357 纬度: 37.400751 地址: 山东省烟台市莱州市206国道 焦家金矿综合门诊部 时间: 2022-08-13 11:10:44</p> <p>经度: 120.131142 纬度: 37.400708 地址: 山东省烟台市莱州市焦家金矿综合门诊部 时间: 2022-08-13 15:08:11</p> <p>经度: 120.144352 纬度: 37.407698 地址: 山东省烟台市莱州市228国道 山东黄金冶炼有限公司 时间: 2022-08-13 14:08:00</p>
DAJC-7F22456~457-2022	合格	2022-8-21	 <p>经度: 120.144352 纬度: 37.407698 地址: 山东省烟台市莱州市228国道 山东黄金冶炼有限公司 时间: 2022-08-21 14:08:00</p>
DAJC-7F22458~500-2022	合格	2022-8-19	 <p>经度: 120.144352 纬度: 37.407698 地址: 山东省烟台市莱州市228国道 山东黄金冶炼有限公司 时间: 2022-08-19 14:08:00</p>

报告编号	结论	报告日期	影像资料
DAJC-7F22501~502-2022	合格	2022-8-11	
DAJC-7F22503~504-2022	合格	2022-8-13	
DAJC-7F22505~506-2022	合格	2022-8-14	
DAJC-7F23154~155-2022	合格	2022-8-5	

报告编号	结论	报告日期	影像资料
DAJC-7F23156-2022	合格	2022-8-7	 <p>经纬度: 120.458227 海拔: 10.1m 地址: 浙江省宁波市江北区 时间: 2022-08-07 10:05:40 天气: 晴</p>
DAJC-7F23157-2022	合格	2022-8-8	 <p>经纬度: 121.093546 海拔: 12.330750 地址: 浙江省宁波市江北区 时间: 2022-08-08 10:05:40 天气: 晴</p>
DAJC-7F23158-2022	合格	2022-8-8	 <p>经纬度: 121.093546 海拔: 12.330750 地址: 浙江省宁波市江北区 时间: 2022-08-08 10:05:40 天气: 晴</p>
DAJC-7F23161-2022	合格	2022-8-18	/
DAJC-7F23170-2022	合格	2022-8-24	 <p>经纬度: 121.093546 海拔: 12.330750 地址: 浙江省宁波市江北区 时间: 2022-08-24 10:05:40 天气: 晴</p>

报告编号	结论	报告日期	影像资料
DAJC-7F23171-2022	合格	2022-8-24	 <p>电话: 120 206886 传真: 77-882221 地址: 山东省烟台市福山区 莱山 邮编: 265205 24062402</p>
DAJC-7F24061-2022	合格	2022-8-14~17	
DAJC-7F24062-2022	合格	2022-8-22~24	
DAJC-7F24064-2022	合格	2022-8-24	

报告编号	结论	报告日期	影像资料
DAJC-7F61143-2022	合格	2022-8-8	
DAJC-7F61144~145-2022	合格	2022-8-18	
DAJC-7F61158-2022	合格	2022-8-25	
DAJC-7F35015-2022	合格	2022-8-30	/
DAJC-7F36016-2022	合格	2022-8-30	/
DAJC-7F38861-2022	合格	2022-8-23	/
DAJC-7F38862-2022	合格	2022-8-23	/
DAJC-7F38863-2022	合格	2022-8-24	/
DAJC-7F38864-2022	合格	2022-8-24	/
DAJC-7F38866-2022	合格	2022-8-24	/
DAJC-7F38867-2022	合格	2022-8-25	/
DAJC-7F38868-2022	合格	2022-8-23	/
DAJC-7F38869-2022	合格	2022-8-25	/
DAJC-7F38870-2022	合格	2022-8-25	/
DAJC-7F38881-2022	合格	2022-8-26	/
DAJC-7F38882-2022	合格	2022-8-26	/
DAJC-7F38883-2022	合格	2022-8-26	/

报告编号	结论	报告日期	影像资料
DAJC-7F38884-2022	合格	2022-8-27	/
DAJC-7F38885-2022	合格	2022-8-27	/
DAJC-7F38886-2022	合格	2022-8-27	/
DAJC-7F38887-2022	合格	2022-8-27	/
DAJC-7F38896-2022	合格	2022-8-31	/
DAJC-7F38899-2022	合格	2022-8-31	/
DAJC-7F38990-2022	合格	2022-8-29	/
DAJC-7F38991-2022	合格	2022-8-29	/
DAJC-7F38992-2022	合格	2022-8-30	/
DAJC-7F38993-2022	合格	2022-8-30	/
DAJC-7F38994-2022	合格	2022-8-31	/
DAJC-7F38995-2022	合格	2022-8-31	/
DAJC-7F46126~132-2022	合格	2022-8-27	/
DAJC-7F46133~136-2022	合格	2022-8-28	/