






报告编号	结论	报告日期	影像资料
DAJC-7M12004-2023	合格	2023-2-9	
DAJC-7M12005-2023	合格	2023-2-10	
DAJC-7M12006-2023	合格	2023-2-6	


报告编号	结论	报告日期	影像资料
DAJC-7M13017~019-2023	合格	2023-2-9	
DAJC-7M13020~022-2023	合格	2023-2-10	
DAJC-7M13023~025-2023	合格	2023-2-6	


报告编号	结论	报告日期	影像资料
DAJC-7M14178~189-2023	合格	2023-2-11	
DAJC-7M14190~205-2023	合格	2023-2-10	
DAJC-7M14206~220-2023	合格	2023-2-11	

报告编号	结论	报告日期	影像资料
DAJC-7M14221~225-2023	合格	2023-2-12	 
DAJC-7M14226~232-2023	合格	2023-2-11	 
DAJC-7M15056~058-2023	合格	2023-2-2	 

报告编号	结论	报告日期	影像资料
DAJC-7M15059~60-2023	合格	2023-2-2	 
DAJC-7M15061~064-2023	合格	2023-2-3	 

报告编号	结论	报告日期	影像资料
DAJC-7M15065~066-2023	合格	2023-2-7	
DAJC-7M15067~068-2023	合格	2023-2-8	
DAJC-7M15077~078-2023	合格	2023-2-6	



报告编号	结论	报告日期	影像资料
DAJC-7M15079-2023	合格	2023-2-8	
DAJC-7M15080~081-2023	合格	2023-2-10	
DAJC-7M15082~089-2023	合格	2023-2-11	

报告编号	结论	报告日期	影像资料
DAJC-7M15090~091-2023	合格	2023-2-12	 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:25:29 备注: 长按水印编辑备注 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:26:59 备注: 长按水印编辑备注
DAJC-7M15092~093-2023	合格	2023-2-9	 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:25:29 备注: 长按水印编辑备注 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:26:59 备注: 长按水印编辑备注
DAJC-7M16126~128-2023	合格	2023-2-2	 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:25:29 备注: 长按水印编辑备注 经度: 116.856712 纬度: 35.772344 地址: 山东省泰安市宁阳县葛石镇 天能电 池 时间: 2023-02-12 08:26:59 备注: 长按水印编辑备注


报告编号	结论	报告日期	影像资料
DAJC-7M16129~131-2023	合格	2023-2-3	
DAJC-7M16132~135-2023	合格	2023-2-7	



报告编号	结论	报告日期	影像资料
DAJC-7M16136~139-2023	合格	2023-2-8	
DAJC-7M16143~147-2023	合格	2023-2-6	 

报告编号	结论	报告日期	影像资料
DAJC-7M16148~149-2023	合格	2023-2-8	
DAJC-7M16150~151-2023	合格	2023-2-10	

报告编号	结论	报告日期	影像资料
DAJC-7M16152~162-2023	合格	2023-2-11	
DAJC-7M16163~167-2023	合格	2023-2-9	
DAJC-7M17032~034-2023	合格	2023-2-10	


报告编号	结论	报告日期	影像资料
DAJC-7M18073~084-2023	合格	2023-2-2	
DAJC-7M18085~096-2023	合格	2023-2-3	



报告编号	结论	报告日期	影像资料
DAJC-7M18098~103-2023	合格	2023-2-6	
DAJC-7M18104~105-2023	合格	2023-2-7	


报告编号	结论	报告日期	影像资料
DAJC-7M18106~113-2023	合格	2023-2-8	
DAJC-7M18114~121-2023	合格	2023-2-9	
DAJC-7M19032~039-2023	合格	2023-2-2	



报告编号	结论	报告日期	影像资料
DAJC-7M19040~043-2023	合格	2023-2-3	 
DAJC-7M19044~051-2023	合格	2023-2-2	 
DAJC-7M19052~057-2023	合格	2023-2-3	 


报告编号	结论	报告日期	影像资料
DAJC-7M19058~073-2023	合格	2023-2-9	
DAJC-7M19074~083-2023	合格	2023-2-6	
DAJC-7M19084~091-2023	合格	2023-2-7	

报告编号	结论	报告日期	影像资料
DAJC-7M19092~108-2023	合格	2023-2-8	
DAJC-7M20018-2023	合格	2023-2-2	
DAJC-7M20019-2023	合格	2023-2-3	

报告编号	结论	报告日期	影像资料
DAJC-7M20020-2023	合格	2023-2-2	
DAJC-7M20021-2023	合格	2023-2-3	



报告编号	结论	报告日期	影像资料
DAJC-7M20022-2023	合格	2023-2-9	
DAJC-7M20023-2023	合格	2023-2-6	 
DAJC-7M20024-2023	合格	2023-2-7	 


报告编号	结论	报告日期	影像资料
DAJC-7M20025-2023	合格	2023-2-8	
DAJC-7M21003-2023	合格	2023-2-2	
DAJC-7M21004-2023	合格	2023-2-3	

报告编号	结论	报告日期	影像资料
DAJC-7M21005-2023	合格	2023-2-6	
DAJC-7M21006-2023	合格	2023-2-9	
DAJC-7M21007-2023	合格	2023-2-11	 经纬: 116.866329 高程: 35.793110 地址: 山东省泰安市宁阳县葛石镇 山东金和矿业集团有限公司 时间: 2023-02-11 14:03:03 备注: 长板水口漏铜渣注 经纬: 116.866329 高程: 35.793110 地址: 山东省泰安市宁阳县葛石镇 山东金和矿业集团有限公司 时间: 2023-02-11 14:03:12 备注: 长板水口漏铜渣注

报告编号	结论	报告日期	影像资料
DAJC-7M22009~031-2023	合格	2023-2-11	 经纬: 116.874884 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-11 02:52:59  经纬: 116.874882 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-11 10:05:19
DAJC-7M22032~033-2023	合格	2023-2-12	 经纬: 116.874884 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-12 10:05:19  经纬: 116.874882 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-12 10:05:19
DAJC-7M23011-2023	所检试件合格	2023-2-7	 经纬: 116.868328 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-07 09:35:52 备注: 环境温度测量  经纬: 116.868328 纬度: 35.792481 地址: 山东省泰安市宁阳县山东金阳矿业集团有限公司 时间: 2023-02-07 09:35:52 备注: 环境温度测量

报告编号	结论	报告日期	影像资料
DAJC-7M24003-2023	合格	2023-2-2~3	
DAJC-7M24004-2023	合格	2023-2-6~12	
DAJC-7M25007~009-2023	合格	2023-2-10	




报告编号	结论	报告日期	影像资料
DAJC-7M67001-2023	合格	2023-2-10	
DAJC-7M67002-2023	合格	2023-2-3	
DAJC-7M38007-2023	合格	2023-2-10	


报告编号	结论	报告日期	影像资料
DAJC-7M38008-2023	合格	2023-2-11	
DAJC-7M38010~011-2023	合格	2023-2-12	
DAJC-7M38017-2023	合格	2023-2-13	


报告编号	结论	报告日期	影像资料
DAJC-7M38018-2023	合格	2023-2-14	
DAJC-7M38019-2023	合格	2023-2-15	
DAJC-7M38020-2023	合格	2023-2-16	


报告编号	结论	报告日期	影像资料
DAJC-7M38021-2023	合格	2023-2-17	
DAJC-7M40003-2023	合格	2023-2-4	
DAJC-7M40004-2023	合格	2023-2-5	

报告编号	结论	报告日期	影像资料
DAJC-7M07006~007-2023	合格	2023-2-22	
DAJC-7M10025~026-2023	符合标准要求	2023-2-22	


报告编号	结论	报告日期	影像资料
DAJC-7M12007-2023	合格	2023-2-20	
DAJC-7M12008-2023	合格	2023-2-19	
DAJC-7M13032~034-2023	合格	2023-2-20	


报告编号	结论	报告日期	影像资料
DAJC-7M13035~038-2023	合格	2023-2-19	
DAJC-7M14233~237-2023	合格	2023-2-17	
DAJC-7M14238~241-2023	合格	2023-2-18	

报告编号	结论	报告日期	影像资料
DAJC-7M14242~259-2023	合格	2023-2-19	
DAJC-7M14260~274-2023	合格	2023-2-20	
DAJC-7M14275~280-2023	合格	2023-2-17	

报告编号	结论	报告日期	影像资料
DAJC-7M14281~286-2023	合格	2023-2-18	
DAJC-7M14287~299-2023	合格	2023-2-17	
DAJC-7M14300~308-2023	合格	2023-2-18	



报告编号	结论	报告日期	影像资料
DAJC-7M15094~095-2023	合格	2023-2-17	
DAJC-7M15096~099-2023	合格	2023-2-18	
DAJC-7M16168~173-2023	合格	2023-2-17	



报告编号	结论	报告日期	影像资料
DAJC-7M16174~179-2023	合格	2023-2-18	
DAJC-7M16180~185-2023	合格	2023-2-19	
DAJC-7M16186~188-2023	合格	2023-2-20	

报告编号	结论	报告日期	影像资料
DAJC-7M17035~038-2023	合格	2023-2-17	 经度: 117.689226 纬度: 35.944017 地址: 山东省泰安市新泰市楼德镇 泰山集团 时间: 2023-02-17 09:02:01 备注: 长按水印删除备注 经度: 117.689226 纬度: 35.944032 地址: 山东省泰安市新泰市楼德镇 泰山集团 时间: 2023-02-17 08:14:25 备注: 长按水印删除备注
DAJC-7M17039~042-2023	合格	2023-2-19	
DAJC-7M17043~045-2023	合格	2023-2-20	


报告编号	结论	报告日期	影像资料
DAJC-7M17047~052-2023	合格	2023-2-18	
DAJC-7M20026~027-2023	合格	2023-2-19	
DAJC-7M20028-2023	合格	2023-2-20	

报告编号	结论	报告日期	影像资料
DAJC-7M21008~009-2023	合格	2023-2-19	
DAJC-7M21010~011-2023	合格	2023-2-20	
DAJC-7M22034~043-2023	合格	2023-2-17	

报告编号	结论	报告日期	影像资料
DAJC-7M22044~054-2023	合格	2023-2-18	 电话: 117 687861 手机: 1344172 地址: 山东省泰安市新泰市前街 山东泰山集团 时间: 2023-02-18 09:35:16 电话: 117 690717 手机: 135 945762 地址: 山东省泰安市新泰市前街 山东泰山集团 时间: 2023-02-18 09:36:37
DAJC-7M24006-2023	合格	2023-2-18~20	 电话: 117 687861 手机: 1344172 地址: 山东省泰安市新泰市前街 山东泰山集团 时间: 2023-02-18 09:35:16 电话: 117 690717 手机: 135 945762 地址: 山东省泰安市新泰市前街 山东泰山集团 时间: 2023-02-18 09:36:37
DAJC-7M25010~013-2023	合格	2023-2-19	


报告编号	结论	报告日期	影像资料
DAJC-7M25014~016-2023	合格	2023-2-20	
DAJC-7M63002-2023	合格	2023-2-22	
DAJC-7M35001-2023	合格	2023-1-29	

报告编号	结论	报告日期	影像资料
DAJC-7M35002-2023	合格	2023-1-30	
DAJC-7M36001-2023	合格	2023-1-30	
DAJC-7M37031-2023	判定该试样的阻燃性能合格	2023-2-10	

报告编号	结论	报告日期	影像资料
DAJC-7M35004-2023	合格	2023-2-12	
DAJC-7M36003-2023	合格	2023-2-12	


报告编号	结论	报告日期	影像资料
DAJC-7M36004-2023	合格	2023-2-13	
DAJC-7M46001~007-2023	合格	2023-2-15	
DAJC-7M35005-2023	合格	2023-2-15	

报告编号	结论	报告日期	影像资料
DAJC-7M36005-2023	合格	2023-2-15	
DAJC-7M46008-2023	合格	2023-2-16	

报告编号	结论	报告日期	影像资料
DAJC-7M35006-2023	合格	2023-2-21	
DAJC-7M35007-2023	合格	2023-2-23	

报告编号	结论	报告日期	影像资料
DAJC-7M36006-2023	合格	2023-2-23	
DAJC-7M39015-2023	合格	2023-2-27	

报告编号	结论	报告日期	影像资料
DAJC-7M39016-2023	合格	2023-2-28	
DAJC-7M35004-2023	合格	2023-2-12	

报告编号	结论	报告日期	影像资料
DAJC-7M35005-2023	合格	2023-2-15	
DAJC-7M35006-2023	合格	2023-2-21	

报告编号	结论	报告日期	影像资料
DAJC-7M35007-2023	合格	2023-2-23	
DAJC-7M36003-2023	合格	2023-2-12	

报告编号	结论	报告日期	影像资料
DAJC-7M36004-2023	合格	2023-2-13	 A black and white photograph showing a person from behind, wearing a light-colored shirt, operating a piece of industrial machinery. The person is holding a handle or lever. Above the person, a sign with the word "EAST" is visible. The background shows a chain-link fence.
DAJC-7M36005-2023	合格	2023-2-15	 A black and white photograph showing a person from behind, wearing a light-colored shirt, operating a piece of industrial machinery. The person is holding a handle or lever. The background shows a chain-link fence.

报告编号	结论	报告日期	影像资料
DAJC-7M36006-2023	合格	2023-2-23	
DAJC-7M37031-2023	判定该试样的阻燃性能合格	2023-2-10	
DAJC-7M38023-2023	合格	2023-2-26	

报告编号	结论	报告日期	影像资料
DAJC-7M38024-2023	合格	2023-2-27	
DAJC-7M39009-2023	合格	2023-2-6	
DAJC-7M39015-2023	合格	2023-2-27	

报告编号	结论	报告日期	影像资料
DAJC-7M39016-2023	合格	2023-2-28	
DAJC-7M46001~007-2023	合格	2023-2-15	
DAJC-7M46008-2023	合格	2023-2-16	