

报告编号	结论	报告日期	图片	备注
DAJC-7F10397-2022	合格	2022-06-21	 经度：119.291441 纬度：44.638695 地址：内蒙古自治区赤峰市巴林左旗 时间：网络获取失败 海拔：1119.0米 天气：☁️ 26 ~ 33℃ 西南风	

DAJC-7F10399-2022	合格	2022-08-31	 经度: 120.845176 纬度: 50.920885 地址: 网络获取失败 时间: 网络获取失败 海拔: 908.7米 天气: 网络获取失败 备注: 长按水印编辑备注	
--------------------------	-----------	-------------------	---	--

DAJC-7F10400-2022

合格

2022-08-31



经度：正在获取中...
纬度：正在获取中...
地址：正在获取中...
时间：网络获取失败
海拔：正在获取中...
天气：网络获取失败
备注：长按水印编辑备注

DAJC-7F10401-2022	合格	2022-08-31	 经度：120.830566 纬度：50.952272 地址：网络获取失败 时间：网络获取失败 海拔：网络获取失败 天气：网络获取失败 备注：长按水印编辑备注
--------------------------	-----------	-------------------	---

DAJC-7F142977-2022

合格

2022-09-02



DAJC-7F15922-2022	合格	2022-09-02	 经度: 120.837749 纬度: 50.917036 地址: 网络获取失败 时间: 网络获取失败 海拔: 844.2米 天气: 网络获取失败 备注: 长按水印编辑备注
--------------------------	-----------	-------------------	--

DAJC-7F15929-2022

合格

2022-09-03



DAJC-7F16951-2022

合格

2022-09-02



DAJC-7F16955-2022

合格

2022-09-03



DAJC-7F22507-2022

合格

2022-09-02



DAJC-7F23173-2022

合格

2022-09-06



经度: 120.940319

纬度: 50.905690

地址: 内蒙古自治区呼伦贝尔市根河市呼
伦贝尔大草原

时间: 2022-09-06 10:00:07

海拔: 759.0米

天气: 8°C 北风 晴

备注: 长按水印编辑备注



经度：正在获取中...
纬度：正在获取中...
地址：正在获取中...
时间：2022-09-06 10:31:36
海拔：正在获取中...
天气：8°C 北风 晴
备注：长按水印编辑备注

DAJC-7F23174-2022

合格

2022-09-06



DAJC-7F24065-2022

合格

2022-09-02



经度：正在获取中...
纬度：正在获取中...
地址：正在获取中...
时间：网络获取失败
海拔：正在获取中...
天气：网络获取失败
备注：长按水印编辑备注

DAJC-7F24066-2022

合格

2022-09-03



DAJC-7F49011-2022

合格

2022-08-07



DAJC-7F50046-2022

合格

2022-08-07



DAJC-7F61159-2022

合格

2022-09-06



经度：120.844325

纬度：50.921693

地址：内蒙古自治区呼伦贝尔市根
河市呼伦贝尔大草原

时间：2022-09-06 14:52:26

海拔：0.0米

天气：☁️ 15 ~ 15°C 西风

元道经纬相机

DAJC-7F69119-2022

合格

2022-07-20



DAJC-7F69120-2022

合格

2022-07-20



DAJC-7F69121-2022

合格

2022-07-20



DAJC-107069-2022

合格

2022-09-02



DAJC-107070-2022	合格	2022-09-03	 经度：120.832844 纬度：50.949903 地址：网络获取失败 时间：网络获取失败 海拔：991.3米 天气：网络获取失败
------------------	----	------------	--

DAJC-130083-2022

合格

2022-09-02



经度：正在获取中...
纬度：正在获取中...
地址：正在获取中...
时间：网络获取失败
海拔：正在获取中...
天气：网络获取失败
备注：长按水印编辑备注

DAJC-130084-2022

合格

2022-09-02



DAJC-130085-2022

合格

2022-09-03



DAJC-130086-2022

合格

2022-08-23



DAJC-7F75051-2022	合格	2022-07-29	 经度：117.837658 纬度：34.850932 地址：山东省临沂市兰陵县光明路 临矿集团会宝岭铁矿公司 时间：2022-07-29 15:31:13 海拔：89.8米 天气：☁️ 25 ~ 28℃ 东风
-------------------	----	------------	--

DAJC-7F75052-2022

合格

2022-07-29



DAJC-7F75053-2022	合格	2022-07-29	 经度：117.837360 纬度：34.851026 地址：山东省临沂市兰陵县光明路临 矿集团会宝岭铁矿公司 时间：2022-07-29 15:48:30 海拔：111.2米 天气：☁️ 25 ~ 28℃ 东风 备注：长按水印编辑备注
-------------------	----	------------	---

DAJC-7F75054-2022	合格	2022-07-29	 经度：117.837780 纬度：34.850760 地址：山东省临沂市兰陵县光明路临 矿集团会宝岭铁矿公司 时间：2022-07-29 14:57:12 海拔：0.0米 天气：☁️ 25 ~ 28℃ 东风 备注：长按水印编辑备注
-------------------	----	------------	---

DAJC-7F75055-2022	合格	2022-07-29	 经度：117.837572 纬度：34.850975 地址：山东省临沂市兰陵县光明路临 矿集团会宝岭铁矿公司 时间：2022-07-29 15:51:21 海拔：126.5米 天气：☁️ 25 ~ 28℃ 东风 备注：长按水印编辑备注
-------------------	----	------------	---

DAJC-7F75060-2022	合格	2022-08-05	 经纬: 120.145778 纬度: 37.431007 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 14:17:31 海拔: 0.0米 天气: 🌤️ 23~34℃ 西南风 📷: 设备水印编辑备注
-------------------	----	------------	--

DAJC-7F75061-2022	合格	2022-08-03	 经度: 120.146538 纬度: 37.431088 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 14:34:57 海拔: 0.0米 天气: ☁️ 33~34°C 西南风 备注: 长按水印编辑备注
-------------------	----	------------	--

DAJC-7F75062-2022	合格	2022-08-03	 纬度: 120.146982 经度: 37.431107 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 14:58:27 海拔: 71.3米 天气: 🌤️ 33~34℃ 西南风 备注: 长镜头编辑备注
-------------------	----	------------	---

DAJC-7F75063-2022	合格	2022-08-03	 经度: 120.146378 纬度: 37.431260 地址: 山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	--

DAJC-7F75064-2022	合格	2022-08-03	 经纬: 120.146109 高程: 97.431081 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 14:35:25 海拔: 0.0米 天气: 🌤️ 33~34℃ 西南风 备注: 长镜头拍摄备注
-------------------	----	------------	--

DAJC-7F75065-2022	合格	2022-08-03	 现场照片 经度：正在获取中 纬度：正在获取中
--------------------------	-----------	-------------------	---

DAJC-7F75066-2022

合格

2022-08-03



DAJC-7F75067-2022	合格	2022-08-03	
-------------------	----	------------	---

DAJC-7F75068-2022	合格	2022-08-03	 经度: 120.145988 纬度: 37.430995 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼
-------------------	----	------------	---

DAJC-7F75069-2022

合格

2022-08-03



DAJC-7F75070-2022	合格	2022-08-03	
-------------------	----	------------	--

DAJC-7F75071-2022	合格	2022-08-03	 经纬: 120.145754 高程: 37.431173 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 16:14:33 海拔: 33.3米 天气: 🌤️ 33~34℃ 南风 备注: 长镜头拍摄备注
-------------------	----	------------	--

DAJC-7F75072-2022

合格

2022-08-03



DAJC-7F75073-2022	合格	2022-08-03	 经度: 120.145750 纬度: 37.431246 地址: 山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	--

DAJC-7F75074-2022	合格	2022-08-03	 现场拍照 经度: 120.145917 纬度: 37.430988 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 15:00:43 海拔: 37.1米
-------------------	----	------------	--

DAJC-7F75075-2022

合格

2022-08-03



经度: 120.145976
纬度: 37.430910
地址: 山东省烟台市莱州市228国道新城金矿采
矿车公棚

DAJC-7F75076-2022	合格	2022-08-03	 经度：120.145873 纬度：37.431430 地址：山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	---

DAJC-7F75077-2022	合格	2022-08-03	 现场拍照 经度: 120.145747 纬度: 37.430805 地址: 山东省烟台市莱州市228国道新城金矿采 矿车检修
-------------------	----	------------	---

DAJC-7F75078-2022	合格	2022-08-03	 现场拍照 经度: 120.145906 纬度: 37.431109 地址: 山东省烟台市莱州市228国道新城金矿采 矿办公楼 时间: 2022-08-03 15:18:42 海拔: 0.0米 天气: ☁️ 33~34°C 南风 备注: 长按水印编辑备注
-------------------	----	------------	--

DAJC-7F75079-2022	合格	2022-08-03	 经度: 正在获取中 纬度: 正在获取中
-------------------	----	------------	---

DAJC-7F75080-2022	合格	2022-08-04	 经度: 120.145780 纬度: 37.430762 地址: 山东省烟台市莱州市228国道新城金矿采 矿点公路
-------------------	----	------------	---

DAJC-7F75081-2022	合格	2022-08-04	 经度: 120.145780 纬度: 37.430896 地址: 山东省烟台市莱州市228国道新城金矿采 矿点
--------------------------	-----------	-------------------	---

DAJC-7F75082-2022

合格

2022-08-04



DAJC-7F75083-2022	合格	2022-08-04	 现场拍照 经度: 120.146398 纬度: 37.430894 地址: 山东省烟台市莱州市228国道新城金矿采 矿点公路
-------------------	----	------------	--

DAJC-7F75084-2022	合格	2022-08-04	 现场拍照 经度: 120.146398 纬度: 37.430894 地址: 山东省烟台市莱州市228国道新城金矿采 矿点公路
-------------------	----	------------	--

DAJC-7F75085-2022	合格	2022-08-04	 经度: 120.145765 纬度: 37.430893 地址: 山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	--

DAJC-7F75086-2022	合格	2022-08-04	 经纬度: 120.146106 车牌: 371431036 地址: 山东省烟台市莱州市228国道新城壹中心 办公大楼 时间: 2022-08-03 09:29:50 海拔: 0.0米 天气: 27~35℃ 东南风 IMEI: 868823032017135 备注: 救护车出车记录
-------------------	----	------------	--

DAJC-7F75087-2022	合格	2022-08-04	 经度: 120.146199 纬度: 37.431064 地址: 山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	--

DAJC-7F75088-2022	合格	2022-08-04	 经度：120.145873 纬度：37.431430 地址：山东省烟台市莱州市228国道新城金矿采
-------------------	----	------------	---