

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
1	143 山东东平宏达矿业有限公司	DAJC-7F38796-2024	2024-9-1	合格	 A photograph of a rock sample, likely a piece of steel wire rope, with a label in front of it. The label contains the following information: 样品名称 (Sample Name): 山东东平宏达矿业有限公司 (Shandong Dongping Hongda Mining Co., Ltd.), 样品编号 (Sample Number): DAJC-7F38796-2024, 样品规格 (Sample Specification): 钢丝绳 (Steel Wire Rope), 检测日期 (Detection Date): 2024.09.01, 检测/型号 (Detection/Model): 6V*34/18, 钢丝绳直径 (Steel Wire Rope Diameter): 18mm, 使用地点 (Usage Location): 东平宏达矿 (Dongping Hongda Mine), 用 途 (Use): 提升 (Lifting).
2	143 山东东平宏达矿业有限公司	DAJC-7F38797-2024	2024-9-1	合格	 A photograph of a rock sample, likely a piece of steel wire rope, with a label in front of it. The label contains the following information: 样品名称 (Sample Name): 山东东平宏达矿业有限公司 (Shandong Dongping Hongda Mining Co., Ltd.), 样品编号 (Sample Number): DAJC-7F38797-2024, 样品规格 (Sample Specification): 钢丝绳 (Steel Wire Rope), 检测日期 (Detection Date): 2024.09.01, 检测/型号 (Detection/Model): 6V*34/18, 钢丝绳直径 (Steel Wire Rope Diameter): 18mm, 使用地点 (Usage Location): 东平宏达矿 (Dongping Hongda Mine), 用 途 (Use): 提升 (Lifting).

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
3	143 山东东平宏达矿业有限公司	DAJC-7F38798-2024	2024-9-2	合格	
4	156 山东黄金矿业股份有限公司新城金矿	DAJC-7F38801-2024	2024-9-3	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
5	164 山东黄金矿业(玲珑)有限公司东风矿区	DAJC-7F38812-2024	2024-9-4	合格	
6	149 金诚信矿业管理股份有限公司瓮安分公司	DAJC-7F38814-2024	2024-9-5	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
7	149 金诚信矿业管理股份有限公司瓮安分公司	DAJC-7F38815-2024	2024-9-6	合格	
8	168 山东黄金矿业(玲珑)有限公司灵山矿区	DAJC-7F38816-2024	2024-9-6	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
9	231 山东金洲矿业集团有限公司金青顶矿区	DAJC-7F38817-2024	2024-9-5	合格	
10	192 中煤五建三处纱岭项目部主井	DAJC-7F38818-2024	2024-9-4	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
11	140 东平县泰兴石料开发有限公司	DAJC-7F46212~214-2024	2024-9-10	合格	
12	146 东平金牛矿业有限公司	DAJC-7F46215~218-2024	2024-9-12	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
13	221 青岛金星矿业股份有限公司	DAJC-7F47434~435-2024	2024-9-6	合格	
14	140 东平县泰兴石料开发有限公司	DAJC-7F47443~445-2024	2024-9-10	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
15	192 中煤五建三处纱岭项目部主井	DAJC-7F81005~006-2024	2024-9-19	合格	
16	193 中煤五建三处纱岭项目部进风井	DAJC-7F81007~008-2024	2024-9-20	合格	

序号	报告名称	报告编号	检测检验时间	报告结论	现场勘验影像资料
17	192 中煤五建三处纱岭项目部主井	DAJC-7F82005~007-2024	2024-9-19	合格	
18	193 中煤五建三处纱岭项目部进风井	DAJC-7F82008~010-2024	2024-9-20	合格	